



EPMA Powder Metallurgy Summer School

27 June – 1 July 2016 - Valencia, Spain



Introduction to Materials Science

Prof. Alberto Molinari

University of Trento, Italy

*Some of the figures used in this presentation were taken from
R.E. Reed-Hill, Physical Metallurgy Principles
2° edition, PWS-KENT Publishing Company, Boston*

alberto.molinari@unitn.it

Why Materials Science ?

The PM process transforms a raw material into a final product through a sequence of operations based on various chemical and structural transformations of the processed metal.

The success of the process depends on the ability to properly manage these transformations, which are studied and explained by Materials Science (and Physical Chemistry).

Materials Science studies the **relationships between the structure/microstructure of a material and its properties**, which influence its behavior when subject to thermal loading, mechanical loading, electrical and magnetic fields, etc.

Physical Chemistry investigates the reactions between a material and any environment in contact with, both in solid and liquid state

Thermodynamics and kinetics

Thermodynamics

Defines the driving force of a transformation and, in general, of all phenomena occurring in materials. The reference is the equilibrium state, defined by a minimum of the Gibbs free-energy **G**. The driving force is the excess of Gibbs free-energy with respect to the equilibrium one, since all the materials tend spontaneously towards the equilibrium.

Kinetics

Defines the rate of a transformation and, in general, of all phenomena occurring in materials. It depends on several parameters but mostly on temperature.

Thermodynamics says if a given transformation may occur or not; kinetics says how fast transformation will occur

Transformations in PM

The conventional PM process

Transformations occurring in the processed metal

Powder production

- in solid state -----> Reaction with the atmosphere
- from a liquid phase -----> Melting and solidification

Shaping

- compaction -----> Elastic and plastic deformation

Sintering

- free sintering -----> Structural transformations activated by temperature
- > Reaction with the atmosphere

Secondary operations

- sizing -----> Plastic deformation
- re-compaction -----> Plastic deformation
- heat treatments -----> Structural transformations activated by temperature
- others

Alternative processes


- Pressure assisted sintering -----> Deformation at high temperature / Structural transformations activated by temperature
- Additive manufacturing -----> Melting and solidification / Structural transformations activated by temperature

The structure of metals



Iron parts for magnetic applications


Micrometric range
Optical microscope; SEM/microanalysis




The **microstructure**: the polycrystalline aggregate. Grains (crystals) and grain boundary

The **structure**: the unit cell
Atoms are organized according to a defined geometrical order

Nanometric range
X-Ray Diffraction



The **structure of atom**
Nucleus and electrons



The formation of the structure of metals


The liquid metal



Solidification with:

- geometrical disorder → amorphous metal
- geometrical order → crystalline metal

The structure





Solidification of a crystalline metal

Nucleation and growth of:

- one single crystal → single crystal
- a population of crystals → polycrystalline aggregate


The microstructure



The same mechanism occurs during solid state transformations, included recrystallization


The structure of metals: the unit cell of crystalline metals

The body-centered cubic
structure
bcc




Examples: iron

The face-centered cubic
structure
fcc



copper-aluminum

The hexagonal closed
packed structure
hcp



titanium

The fcc and hcp metals are tendencially more ductile than the bcc ones

The crystal structure of metals: defects

Any imperfection in the regular packing of atoms

Vacancies

Interstitial atoms


Substitutional atoms

Dislocations

Stacking faults

Twins / twin boundaries

Grain boundary



The crystal structure of metals: defects

Any imperfection in the regular packing of atoms

Vacancies

Interstitial atoms (carbon and nitrogen in iron)


Substitutional atoms

Dislocations

Stacking faults

Twins / twin boundaries

Grain boundary



The crystal structure of metals: defects

Any imperfection in the regular packing of atoms

Vacancies

Interstitial atoms


Substitutional atoms (Cr, Ni, Mo,... in iron)

Dislocations

Stacking faults

Twins / twin boundaries

Grain boundary



The crystal structure of metals: defects



Any imperfection in the regular packing of atoms

Vacancies
Interstitial atoms
Substitutional atoms

Dislocations

Stacking faults
Twins /twin boundaries


Grain boundary



The crystal structure of metals: defects

Any imperfection in the regular packing of atoms

Vacancies
Interstitial atoms
Substitutional atoms




Dislocations

Stacking faults

Twins / twin boundaries

Grain boundary



The crystal structure of metals: defects

Any imperfection in the regular packing of atoms

Vacancies

Interstitial atoms



Substitutional atoms

Dislocations

Stacking faults

Twins / twin boundaries

Grain boundary



The crystal structure of metals: defects



Any imperfection in the regular packing of atoms

Vacancies
Interstitial atoms
Substitutional atoms

Dislocations

Stacking faults
Twins / twin boundaries

Grain boundary



Transformations in PM

The conventional PM process

Powder production

- in solid state -----> Reaction with the atmosphere
- **from a liquid phase** -----> **Melting and solidification**

Shaping

- compaction -----> Elastic and plastic deformation

Sintering

- free sintering -----> Structural transformations activated by temperature
- > Reaction with the atmosphere

Secondary operations

- sizing -----> Plastic deformation
- re-compaction -----> Plastic deformation
- heat treatments -----> Structural transformations activated by temperature
- others


Alternative processes

- Pressure assisted sintering -----> Deformation at high temperature / Structural transformations activated by temperature


- Additive manufacturing** -----> **Melting and solidification** / Structural transformations activated by temperature

Transformations occurring in the processed metal

Solidification: the liquid-solid transformation




Nucleation and growth of a population of crystals. At temperature below T_0



The higher the undercooling, the higher the nucleation rate, the smaller the size of the solid crystals




Metallic powders produced by atomization of a liquid have a very fine microstructure





Solidification: the liquid-solid transformation

In additive manufacturing processes, as Selective Laser Melting, undercooling is very high and the microstructure results very fine



As-built microstructure of Ti6Al4V alloy, very brittle and unacceptable

..... much finer than after conventional sintering



Transformations in PM

The conventional PM process

Powder production

- in solid state -----> Reaction with the atmosphere
- from a liquid phase -----> Melting and solidification

Shaping

- **compaction** -----> **Elastic and plastic deformation**

Sintering

- free sintering -----> Structural transformations activated by temperature
- > Reaction with the atmosphere

Secondary operations

- **sizing** -----> **Plastic deformation**
- **re-compaction** -----> **Plastic deformation**
- heat treatments -----> Structural transformations activated by temperature
- others


Alternative processes

- Pressure assisted sintering -----> Deformation at high temperature / Structural transformations activated by temperature
- Additive manufacturing -----> Melting and solidification / Structural transformations activated by temperature

Transformations occurring in the processed metal

Elastic and plastic deformation of metals


The tensile test



F = force (N)
 A = cross section (mm^2)
 l_0 = length of a segment (mm)


$\sigma = F/A$ = stress (MPa)
 $\varepsilon = (l - l_0)/l_0 = \Delta l/l_0$ = strain (%)

The tensile stress-strain curve



Elastic and plastic deformation of metals

Elastic deformation





Elastic and plastic deformation of metals

During compaction, powder are deformed plastically (by a compressive stress).

Elastic deformation does not provide any densification and strength.

The compaction curve of two iron powders





Microstructure and




..... fracture surface of a green part

Plastic deformation of metals

Plastic deformation occurs by slip of the lattice planes caused by a shear stress



Slip of the lattice planes occurs by the movement (gliding) of dislocations



Plastic deformation of metals

The shear stress to promote slip
(Nabarro Peierls shear stress)

$$\tau_{NP} = \frac{2G}{(1-\nu)} e^{-[2\pi a/(1-\nu)b]}$$


..... depends on:

- distance between planes (a) and atoms (b)
- temperature (through G)
- impurities

It increases with the content of impurities, and for this reason the chemical quality of the powders influences compressibility

It decreases on increasing temperature, and for this reason plastic deformation is enhanced on increasing temperature (warm/hot compaction)

It depends on the crystal structure; it is tendentially smaller in fcc crystals, and for this reason metals with fcc structure are more ductile than the other ones, and their powders have a better compressibility



Plastic deformation of metals



The resistance to plastic deformation of a metal depends on:

1. **The density of dislocation in the crystal (strain hardening)**
2. The grain size (grain refining)
3. The content of alloying elements (solution hardening)
4. The presence of precipitates (precipitation hardening)

Dislocation density ρ increases during plastic deformation, and this increases the stress required to move dislocations.



For this reason the compaction curve decreases its slope continuously and the full density cannot be attained




Plastic deformation of metals

The resistance to plastic deformation of a metal depends on:

1. The density of dislocation in the crystal (strain hardening)
- 2. The grain size (grain refining)**
3. The content of alloying elements (solution hardening)
4. The presence of precipitates (precipitation hardening)

The stress to promote plastic deformation increases when grain size (D) decreases




For this reason, grain growth which may occur on sintering, has to be prevented to preserve mechanical strength of the sintered parts

Plastic deformation of metals


The resistance to plastic deformation of a metal depends on:

1. The density of dislocation in the crystal (strain hardening)
2. The grain size (grain refining)
- 3. The content of alloying elements (solution hardening)**
4. The presence of precipitates (precipitation hardening)

The stress to move dislocations increases in presence of alloying elements



This is the reason why alloys have less compressibility than pure metals and compressibility decreases with the content of alloying elements




Plastic deformation of metals

The resistance to plastic deformation of a metal depends on:

1. The density of dislocation in the crystal (strain hardening)
2. The grain size (grain refining)
3. The content of alloying elements (solution hardening)
- 4. The presence of precipitates (precipitation hardening)**

The stress to move dislocations increases in presence of precipitates, in particular if they are submicrometric



This mechanism is used in some technological alloys, the most important example are aluminum alloys. The effect is obtained by means of a specific heat treatment: Precipitation-hardening

Transformations in PM

The conventional PM process

Transformations occurring in the processed metal

Powder production

- in solid state -----> Reaction with the atmosphere
- from a liquid phase -----> Melting and solidification

Shaping

- compaction -----> Elastic and plastic deformation

Sintering

- **free sintering** -----> **Structural transformations activated by temperature**
- > Reaction with the atmosphere

Secondary operations

- sizing -----> Plastic deformation
- re-compaction -----> Plastic deformation
- heat treatments -----> Structural transformations activated by temperature
- others

Alternative processes

- Pressure assisted sintering -----> Deformation at high temperature / Structural transformations activated by temperature
- Additive manufacturing -----> Melting and solidification / Structural transformations activated by temperature


Structural transformations activated by temperature: Diffusion

Diffusion is a mass transport phenomenon involving single atoms, which tends to eliminate concentration gradients in metals.

It is activated by temperature in presence of :


- Vacancies concentration gradients (self-diffusion)
- Impurities/alloying elements concentration gradients (interstitial/substitutional diffusion)

Vacancies concentration gradients




→
Self-diffusion

Homogeneous distribution of vacancies




Structural transformations activated by temperature: Diffusion

Interstitial concentration gradients




**Interstitial
diffusion**

Homogeneous distribution of interstitials




Substitutional concentration gradients




**Substitutional
diffusion**

Homogeneous distribution of substitutionals



Structural transformations activated by temperature: Diffusion



In presence of a (vacancies/atoms) concentration gradient $\delta C_B / \delta x$, a flux J_B of B is activated which tends to eliminate the gradient leading to a homogeneous distribution of vacancies/atoms

$$J_B = -D_B \delta C_B / \delta x$$

D_B = diffusion coefficient of B in the metal M

B = vacancies \longrightarrow self-diffusion

B = other atoms \longrightarrow diffusion of B in M

} depend on temperature

$$D = D_0 e^{(-Q/RT)}$$

Structural transformations activated by temperature: Diffusion

Different diffusion paths

Surface diffusion


$$D_s = D_{s,0} e^{(-Q_s/RT)}$$

Grain boundary diffusion

$$D_{gb} = D_{gb,0} e^{(-Q_{gb}/RT)}$$


Volume (lattice) diffusion

$$D_v = D_{v,0} e^{(-Q_v/RT)}$$



The main sintering mechanism is diffusion due to a vacancies concentration gradient between the neck and the bulk of the particles (**self-diffusion**)

In alloys produced by blends of elemental powders, **diffusion of alloying elements** is activated and **contributes to sintering**



Structural transformations activated by temperature: Grain growth




Grain growth is a temperature activated phenomenon which leads to a progressive increase in the mean grain size.

It occurs during sintering and heat treatments.

The **driving force** of grain growth is the Gibbs free energy ΔG associated to the grain boundary surface ΔS

$$\Delta G = \gamma_{gb} \Delta S$$

which can be decreased only if the grain boundary surface decreases




Structural transformations activated by temperature: Grain growth


The **mechanism** of grain growth is **diffusion** coupled to **grain boundary migration**

The **grain growth kinetics**


$$D^2 - D_0^2 = K_0 e^{(-Q/RT)} t$$



Diffusion



Grain boundary migration




Structural transformations activated by temperature: Grain growth

Grain growth causes a decrease of mechanical properties of materials, therefore it should be either avoided or, at least, minimized.

Grain growth is slowed down and sometimes inhibited by the presence of particles of second phases on the grain boundary

The same effect is provided by pores in sintering



Transformations in PM

The conventional PM process

Powder production

- in solid state -----> Reaction with the atmosphere
- from a liquid phase -----> Melting and solidification

Shaping

- compaction -----> Elastic and plastic deformation

Sintering

- free sintering -----> Structural transformations activated by temperature
- > Reaction with the atmosphere

Secondary operations

- sizing -----> Plastic deformation
- re-compaction -----> Plastic deformation
- heat treatments -----> Structural transformations activated by temperature
- others

Alternative processes

Pressure assisted sintering -----> Deformation at high temperature / Structural transformations activated by temperature


Additive manufacturing -----> Melting and solidification / Structural transformations activated by temperature

Transformations occurring in the processed metal

Plastic deformation at high temperature

At high temperature plastic deformation of metals is enhanced since:


1. **The stress to move dislocations decreases with temperature**
2. The strain hardening is eliminated by recovery and mainly by recrystallization, which decrease the density of dislocations



Plastic deformation at high temperature

At high temperature plastic deformation of metals is enhanced since:

1. The stress to move dislocations decreases with temperature
2. **The strain hardening is eliminated by recovery and mainly by recrystallization**, which decrease the density of dislocations



Increasing temperature




Dislocation density decreases – resistance to plastic deformation decreases

Plastic deformation at high temperature

At high temperature plastic deformation of metals is enhanced since:


3. A new deformation mechanism is activated: creep



Creep:


time depending permanent deformation occurring at high temperature under a constant load, due to:

1. volume diffusion (Nabarro-Herring)
2. grain boundary diffusion (Coble)
3. dislocation motion by climbing (power law)



Deformation = densification

Densification during pressure-assisted sintering techniques is the result of the combination/sequence of deformation at high temperature and diffusion



Transformations in PM

The conventional PM process

Transformations occurring in the processed metal

Powder production

- in solid state -----> Reaction with the atmosphere
- from a liquid phase -----> Melting and solidification

Shaping

- compaction -----> Elastic and plastic deformation

Sintering

- **free sintering** -----> **Structural transformations activated by temperature**
- > Reaction with the atmosphere

Secondary operations

- sizing -----> Plastic deformation
- re-compaction -----> Plastic deformation
- heat treatments -----> Structural transformations activated by temperature
- others

Alternative processes

- Pressure assisted sintering -----> Deformation at high temperature / Structural transformations activated by temperature

- Additive manufacturing** -----> Melting and solidification / **Structural transformations activated by temperature**

Structural transformations activated by temperature: Phase transformations.

The case of steel

Some of the metals have different “allotropic” forms in solid state.

Iron, for instance, is:

- bcc up to 912°C (α iron)
- fcc from 911°C up to 1394°C (γ iron)
- bcc from 1392°C up to the melting temperature (1536°C) (δ iron)

These transformations occur on heating and cooling (solid state transformations)


Carbon is added to iron to produce steel. The solubility of carbon in iron is strongly dependent on the allotropic form: much higher in the fcc (austenite) than in the two bcc ones (α and δ ferrite). Above the solubility limit, carbon forms cementite Fe_3C .

Moreover, the presence of carbon:


- affects the temperatures at which the solid state transformations occur
- promotes the formation of “non equilibrium” constituents on cooling of austenite

All these phenomena are described by the Fe-C phase diagram and by the CCT curves of austenite

The Iron-carbon phase diagram




The microstructure of steel: slow cooling



The microstructure of steel: increasing cooling rate

Upper bainite



Lower bainite



Martensite



Increasing cooling rate


The properties of the microstructural constituents: hardness

On increasing hardness

- both yield strength and fatigue strength tendentially increase ,
- ductility decreases (brittleness increases),

- but:

1. Lower bainite is harder and less brittle than upper bainite
2. **Martensite is definitely too brittle**, therefore it cannot be used in practical applications; a **tempering treatment is mandatory to reduce its brittleness (tempered martensite)**




The CCT diagrams

They describe the transformations of austenite on continuous cooling, as that occurring in heat treatments and in sintering


Since the transformations of austenite on continuous cooling depend on:

- carbon content
- alloying elements
- austenite grain size

each steel has its own CCT diagram, which depends on the temperature from which cooling starts



The transformations of austenite



Introduction to Materials Science



Thank you for your kind attention and.....

..... have a nice School

alberto

